



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:

OGM	Jim Smith	Environmental Scientist III
Company	Dennis Oakley	Environmental Engineer

Inspection Report

Permit Number:	C0150017
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, September 28, 2005
Start Date/Time:	9/28/2005 8:27:00 AM
End Date/Time:	9/28/2005 10:05:00 AM
Last Inspection:	Wednesday, August 24, 2005

Inspector: Jim Smith, Environmental Scientist III

Weather: Steady, light rain; cool

InspectionID Report Number: 745

Accepted by: whedberg
9/29/2005

Permittee: **PACIFICORP**

Operator: **ENERGY WEST MINING CO**

Site: **DES BEE DOVE MINE**

Address: **PO BOX 310, HUNTINGTON UT 84528**

County: **EMERY**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **RECLAIMED**

Current Acreages

154.86	Total Permitted
23.88	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☒ Federal
☐ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Rain made the road to the Sedimentation Pond too muddy to access without possibly damaging the road or vehicle, so the pond was inspected at a distance from the adjacent paved county road. Also because of the mud, the upper areas of the reclaimed mine site, accessible by the cattle trail, were not visited this month. The sedimentation pond and road, the soil-pile diversion and ASCA, and the upper areas of the reclaimed mine site were all visited and inspected in August.

Inspector's Signature

Date Wednesday, September 28, 2005

Jim Smith, Environmental Scientist III

Inspector ID Number: 43

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0150017

Inspection Type: COMPLETE

Inspection Date: Wednesday, September 28, 2005

Inspection Continuation Sheet

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

A new permit has been issued, dated 29 August 2005. The copy at the mine was not signed. Permitted area is approximately 154.86 acres. The Permittee is in compliance with the two permit conditions: to submit water-quality data electronically and not to dispose of asphalt on USFS land.

2. Signs and Markers

The paint on the sign at the turnaround has been partially effaced by shotgun pellets, but it is still readable. The adjacent USFS sign, limiting access to motorized vehicles, has been damaged by small caliber firearms.

4.a Hydrologic Balance: Diversions

The diversion at the soil pile was not visited because of the muddy road. This diversion was adequate and functional when checked in August.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee inspected the sedimentation pond 30 June 2005: there was 0.40 acre-ft of sediment storage remaining. At the time of the Division's inspection, rain made the road to the Sedimentation Pond too muddy to access without damaging the road, so the pond was inspected from the adjacent county road. Runoff from rain was filling the bottom of the sedimentation pond, and planned reclamation may need to be delayed to allow the pond-bottom sediment to dry again.

4.c Hydrologic Balance: Other Sediment Control Measures

The soil pile ASCA was not visited because of the muddy road. The soil pile ASCA was functional and adequate when checked in August.

4.d Hydrologic Balance: Water Monitoring

UPDES discharge from the sedimentation pond is the only water monitored at this site. The July UPDES report showed No Discharge. Water was pumped from the pond in August. The August DMR has not been filed with Water Quality yet.

4.e Hydrologic Balance: Effluent Limitations

See 4d. Water Monitoring.

16.a Roads: Construction, Maintenance, Surfacing

At the time of the Division's inspection, rain had made the road to the Sedimentation Pond too muddy to access without possibly damaging the road or vehicle. The road maintenance and surfacing were adequate when inspected in August.

16.b Roads: Drainage Controls

The road drainage controls were adequate and functional when checked in August.

Permit Number: C0150017

Inspection Type: COMPLETE

Inspection Date: Wednesday, September 28, 2005

Inspection Continuation Sheet

Page 4 of 4

21. Bonding and Insurance

The insurance was reissued by Associated Gas and Electric Insurance Services, Ltd., dated from 1 April 2005 to 1 April 2006. It is identical to the previous policy except for the date. Details of the surety bond, # 103771512, are described in the March 2005 inspection report.